

1 / 12




FIG. I

10/538064

2/12




FIG. 2




FIG. 3
ART 34 AMDT

10/538064

3/12




FIG. 4




FIG. 5

ART 34 AMDT

4/12




FIG. 6

5 / 12




FIG. 7a




FIG. 7b

10/538064

6/12




FIG. 8

10/538064

7/12





FIG. 9b

FIG. 9a

10/538064

8/12






FIG. 10

9/12



$$\begin{aligned} Ar=0 &: 4.8 \times 10^{10} \pm 50.0\% \\ Ar=200 &: 6.5 \times 10^{10} \pm 13.6\% \\ Ar=400 &: 8.2 \times 10^{10} \pm 11.3\% \end{aligned}$$

FIG. 11



$$\begin{aligned} Ar=0 &: 4.9 \times 10^{10} \pm 35.2\% \\ Ar=240 &: 6.8 \times 10^{10} \pm 5.7\% \end{aligned}$$

FIG. 12

10/12




FIG. 13

10/538064

11/12




FIG. 14

12/12




FIG. 15a




FIG. 15b